

Changelog between builds 405 and 544:

Category	Summary	Ticket ID	Type
Alarms	Corrected runtime behavior with alarm with live tag inside description - Case ID: 202204369	JM-19289	Bug
Alarms	Wrong size of Live tag calculation in alarms - Case ID: 201805693	JM-14271	Bug
Alarms	Live tag values are not changing when we have only one tag in alarm description	JM-7814	Bug
Behavior	Corrected behavior in continuous page change - Case ID: 202404141	JM-21308	Bug
Behavior	Corrected behavior when closing a dialog inside another dialog - Case ID: 202404141	JM-21307	Bug
Behavior	Encrypted project on HMI with fastboot is not starting - Case ID: 202402678	JM-21099	Bug
Behavior	Fixed handling of malformed TLS packet on port 990/tcp	JM-20987	Bug
Behavior	Fixed handling multiple TCP connections on port 502/tcp	JM-20986	Bug
Behavior	Fixed handling of malformed FTP packet on ports 21/tcp and 990/tcp	JM-20983	Bug
Behavior	Corrected Simulator behavior when Disable Page Cache property is set to true - Case ID: 202404141	JM-21394	Bug
Behavior	Corrected behavior in print function with schedulers in project - Case ID: 202403649	JM-21348	Bug
Behavior	Corrected data transfer behavior using bidirectional mode - Case ID: 202402159	JM-21037	Bug
JM4Web	JM4Web: Fixed alarm status translation - Case ID: 202403223	JM-21340	Bug
JM4Web	JM4Web: Fixed Project validator keeping running in specific scenario - Case ID: 202303577	JM-20284	Bug
JM4Web	JM4Web: Project shows login page with force remote login disabled - Case ID: 202300099	JM-19726	Bug
JM4Web	JM4Web: Corrected behavior of actions not executed until reloading the page - Case ID: 202404973	JM-21404	Bug

JM4Web	JM4Web: Corrected behavior accessing to main page in specific project - Case ID: 202404361	JM-21370	Bug
JM4Web	JM4Web: Table widget not loading on web when its not configured with data source	JM-21362	Bug
JM4Web	JM4Web: Custom widget link change after adding internal widget - Case ID: 202300794	JM-19831	Bug
Protocols	[KEKV] Wrong command used to access unsigned data type - Case ID: 202404997	JM-21393	Bug
Protocols	[J193] When a PGN is designed with less byte than 8 protocol send only byte defined - Case ID: 202404663	JM-21355	Bug
Protocols	[XPLS] Corrected missing deploy of protocol folder - Case ID: 202404086	JM-21327	Bug
Protocols	[PING] Status tag changes to true while pinged device is offline - Case ID: 202404110	JM-21309	Bug
Protocols	[XPLS] Corrected communication issue at project download - Case ID: 202404086	JM-21294	Bug
Protocols	[CCMP] The communication protocol CT Modbus CMP doesn't work on 64bit panel and return communication error - Case ID: 202403936	JM-21278	Bug
Protocols	[BEAD] Importer does not import mono-dimensional array with 512 element size - Case ID: 202403826	JM-21253	Bug
Protocols	[ETIP] Tag missing when imported in linear mode than hierarchical mode - Case ID: 202402566	JM-21242	Bug
Protocols	[ETIP] NAK error returned writing a bool array of a UDT custom - Case ID: 202500139	JM-21456	Bug
Protocols	[CDS3] While having another protocol instance disconnected toggle action take time to be executed - Case ID: 202403281	JM-21240	Bug
Protocols	[CANM] Error Writing after the end of memory type using INT-32 and FLOAT data Type - CaseID: 202403542	JM-21239	Bug
Protocols	[BACN] The Notification Class Count value caused the HMI to crash - CaseID: 202403495	JM-21191	Bug
Protocols	[BACN][BAC2] Multistate value on Bacnet server wrong default - Case ID: 202403329	JM-21168	Bug

Protocols	[MAFP] Different string handling between PLC FPOH and Exor HMI - Case ID: 202301579	JM-21167	Bug
Protocols	[PAFP] protocol version 152 not reading variable correctly - Case ID: 202403246	JM-21162	Bug
Protocols	[DSER] Corrected behavior in case of handling more than 1000 chars - Case ID: 202402787	JM-21132	Bug
Protocols	[KEKV] When using keyence KV protocol with the PLC Network configuration communication doesn't works - Case ID: 202402719	JM-21112	Bug
Protocols	[MIQE] When importing a .xml file generated with GXWorks3, string variables are not imported - Case ID: 202402488	JM-21078	Bug
Protocols	[S7OP] JMobile returns "Failed to load TIA Project symbols" message trying to imports tag from a TIA19 customer's project - Case ID: 202402041	JM-21063	Bug
Protocols	[BEAD] Importer does not import multidimensional array - Case ID: 202400784	JM-21023	Bug
Protocols	[BEAD] HMI can't read Tag string more than 1000 char - Case ID: 202404853	JM-21406	Bug
Protocols	[ETIP] Importing TIME variables from Micro800 sets a wrong tag data type - Case ID: 202400835	JM-20847	Bug
Protocols	[KEKV] Fixed reading issue in serial protocol - Case ID: 202401143	JM-20829	Bug
Protocols	[BACN][BAC2] BacNet max MS/TP APDU can't be lower than 256 - Case ID: 202301869	JM-20005	Bug
Protocols	[J193] DM1 Converion Method ignored for Motorola data format - Case ID: 202500245	JM-21455	Bug
Widgets	JM4Web: Fixed "Wrap Anywhere" option behavior	JM-21361	Bug
Widgets	Action configured on button not executed in specific conditions - Case ID: 202402595	JM-21102	Bug
Alarms	Extend number of char into alarm description	JM-21080	Task
Generic	Add official support to X7 Wired /X10 Wired in JMobile	JM-21479	Task
Generic	Reviewed legal notices	JM-21313	Task

Generic	"Exor International S.p.A." certificate to sign JMobile application (.DLL)	JM-21248	Task
Generic	Adding support for the download of the Machine.ini file on the Manage Target Board of JMobile Studio - Case ID: 202403065	JM-21146	Task
JM4Web	JM4Web: Extend number of char into alarm description	JM-21342	Task
Security	Add Session ID to Audit Trails to identify simultaneous users connected via Web - Case ID: 202400344	JM-20771	Task